

MATERIALS

Commutator bars: oxygen-free copper, silver-bearing copper, solid silver

Insulation between bars: Mica

Moulding compound: phenolic resin

Reinforced rings: steel or glass epoxy

Bushings: steel, brass and spiral

Electro tin or silver plating: This is for improvement of soldering or fusing.

